

Work Alone

TASK specific

Entry into feed mixer wagon or truck for authorized and approved work.

NO HOT WORK

- Check in will be every 20 minutes
- Check in may be continuous monitoring when working with a stand by person who remains outside of the mixer and has constant ability to monitor your activity and has the capacity and ability to effect rescue response.
- The stand by or check in person must be able to:
 - Contact and effect a rescue response
 - Have the capacity and means to make phone calls or use other predetermined and acceptable means of calling for assistance
 - Check in will be by means of:
 - Physical observation and physical presence
 - Two-way radio
 - Cellphone
 - Visible signal to an observing party
 - By spot locator or similar type communication device
- Worker will advise when entering the unit and when they have exited the unit.
- Contact, monitoring, standby person, check in person will record the time of entry and exit for record keeping purposes.

